



FIG. 2




FIG. 3




FIG. 4




FIG. 5




Figure 1 is a perspective view of a multi-layered structure. It shows a stack of layers with a sawtooth profile. Labels include 1, 2, 3, 4, 11, 12, 14, 21, 22, 24, Aa, Ab, and  $Z_3$ . Brackets group layers 11 and 12 as '1', and layers 21 and 22 as '2'.

FIG. 7




FIG. 8







FIG. 9






FIG. 11




FIG. 12




FIG. 13






FIG. 15




FIG. 16






FIG. 17





FIG. 18






FIG. 20




FIG. 21




FIG. 22






FIG. 24








FIG. 26




FIG. 27




FIG. 28






FIG. 30




FIG. 31




FIG. 32






FIG. 33




FIG. 34







FIG. 36



**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☒ FADED TEXT OR DRAWING
- ☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☐ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**